

Annual Report 2022

January 2022



Annual Report 2022

January 2022



Source: Kilcreggan Pier, Copyright Gavin Walker, Pier Master

Contents

1	Introduction	1
2	Port Marine Safety Code	1
	2.1 Argyll and Bute Council and the Code	2
	2.2 Assurance Audits	2
3	Audit outcomes	2
	3.1 Assurance Audit Outcome	4
4	Delivery Plan and Activities	4
5	Designated Person Summary	5
6	References	5
7	Abbreviations/ Acronyms	5

2.1 Argyll and Bute Council and the Code

Argyll and Bute Council is both a Statutory Harbour Authority and a marine asset owner at facilities located throughout the Council area. The Council is the Statutory Harbour Authority at the following locations:

Oban North & South Pier, by virtue of the Oban Pier and Harbour Orders 1862 to 1

Dunoon The Pier and Harbour Orders Confirmation

Campbeltown Harbour Acts and Orders 1846 to 2011

The Council is the marine asset owner and, in most cases, operator at a further 35 piers, wharves and

No	Ten Key Measur	es Required for Successful Implementation of the Code	RAG
4	Duties and Powers	Marine environmental policy lacks details, training for staff on environment duties is not in place. Oil pollution exercises at Helensburgh or Kilcreggan Pier should be introduced.	
5	Marine Risk Assessment	There are no marine risk assessments for either Helensburgh or Kilcreggan Piers. There is no documented stakeholder engagement on marine risk assessments.	

Training:

o 14 May 2021: Duty Holder half-

Contact Us

Ouayelde Suite. Medina Chambers Town Outy, Southamoto

